

TO BE FILLED BY THE INSPECTING OFFICER


1. Name of School : Sree Narayana Vidhya Mandir Senior Secondary School, Talap.
2. Name of Officer : Biju PV
3. Location : Talap, Kannur North
4. Period for which the certificate is issued : 2020-21 Academic year
5. Types of building : RCC structure Permanent - UP school building
6. Nature of defect if any
- a) Foundation and basement : Nil
 - b) Super structure : Nil
 - c) Doors and windows : Nil
 - d) Wood work wrought and put up : Nil
 - e) Roof : Nil
 - f) Flooring : Nil
 - g) Miscellaneous : Nil
7. Any major defects notice which will render the building unsafe in any manner : Nil
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound for conducting classes under normal weather conditions : Yes. The structure is sound for conducting classes under normal weather conditions.

- Note: 1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by on 26/7/2020 and found to be fit to conduct classes for the period for the reasons stated above

Place: Kannur
Date: 26/7/2020


PRINCIPAL
Sree Narayana Vidya Mandir
Senior Secondary School
TALAP, KANNUR-2


Signature
Designation **ASST EXECUTIVE ENGINEER**
PRESIDENT
LOCAL SELF GOVERNMENT DEPARTMENT
Sree Narayana Vidya Mandir
Senior Secondary School
TALAP, KANNUR-2
KANNUR MUNICIPAL CORPORATION

TO BE FILLED BY THE INSPECTING OFFICER

1. Name of School : Sree Narayana Vidhya Mandir Senior Secondary School, Talap
2. Name of Officer : Biju P V
3. Location : Talap, Kannur
4. Period for which the certificate is issued : 2020-21 academic year
5. Types of building : RCC structure (Main building GF+3)
Permanent
6. Nature of defect if any
- | | | | | | |
|---------------------------------|---|---|-----|--|--|
| a) Foundation and basement | : | } | Nil | | |
| b) Super structure | : | | | | |
| c) Doors and windows | : | | | | |
| d) Wood work wrought and put up | : | | | | |
| e) Roof | : | | | | |
| f) Flooring | : | | | | |
| g) Miscellaneous | : | | | | |
- GF - 8.80 X 21.00 X 3.60
9.00 X 21.30 X 3.60
24.80 X 9.20 X 3.60
13.20 X 6.00 X 3.00 (Toilet block)
- FF } 8.80 X 21.00 X 3.60
SF } 9.00 X 21.30 X 3.60
TF } 24.80 X 9.20 X 3.60
7. Any major defects notice which will render the building unsafe in any manner : Nil
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound for conducting : Yes. The structure is sound for conducting classes under normal weather conditions.

- Note: 1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by on 26/7/2020 and found to be fit to conduct classes for the period for the reasons stated above

Place : Kannur
Date : 26/7/2020

PRINCIPAL
Sree Narayana Vidya Mandir
Senior Secondary School
TALAP, KANNUR-2

Signature _____
Designation _____
ASST EXECUTIVE ENGINEER
PRESIDENT LOCAL SELF GOVERNMENT DEPARTMENT
Sree Narayana Vidya Mandir
Senior Secondary School
TALAP, KANNUR-2

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer / Assistant Executive Engineer)

Name of School Sree Narayana Vidya Mandir, Senior Secondary School, Talap, Kannur (L.P Block Only)

1. Name of the Officer Prakash Babu M Assistant Executive Engineer

2. Location Pallikunnu Zonal

3. Period for which the certificate is issued 2020-21 29-9-20 to 31/3/2021

4. Types of building Permanent Multi storied (Building No. V-1115-2002) L.P Block

5. Nature of defect if any

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

Area of Building (RCC Building)

GF = $34.00 \times 8.47 = 288m^2$ 3.60ht

FR = $34.00 \times 7.85 = 266.9m^2$ 3.60ht

SF = $34.00 \times 7.85 = 266.90m^2$ 3.60ht

Third Floor - $34.00 \times 7.85 = 266.90m^2$ 3.60ht

No Total area 1088.70m²

6. Any major defects noticed which will render the building unsafe in any manner No

7. Whether maintenance work have been done properly Yes

8. Whether the structure is sound or not for conducting classes. The structure is safe and sound for conducting classes under normal wind and weather conditions

Note: 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2 Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate.

Certified that the School was inspected by me on 25/9/2020 and found to be, fit / unfit to conduct classes for the period for the reasons stated above.

Kannur
PRINCIPAL
Sree Narayana Vidya Mandir
Senior Secondary School
TALAP KANNUR-2

Prakash Babu M
PRESIDENT
Sree Narayana Vidya Mandir
Senior Secondary School
TALAP KANNUR-2

[Signature]
ASST. EXECUTIVE ENGINEER - III
LOCAL SELF GOVERNMENT DEPARTMENT
KANNUR MUNICIPAL CORPORATION