

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- Name of the School : Sree Narayana Vidya Mandir Senior Secondary School, Talap
1. Name of the Officer : Sree Krishna Puthussery
2. Location : Talap, Kannur.
3. Period for which the certificate is issued : 2021-22 Academic year.
4. Types of building : R.C.C. structure (Main building)
5. Nature of defect if any : Permanent - GF + 3
- a) Foundation and basement : } Nil
- b) Superstructure : } GF - 8.80 x 21.00 x 3.60
- c) Doors and windows : } 9.00 x 21.30 x 3.60
- d) Wood work wrought and put up : } 24.80 x 9.20 x 3.60
- e) Roof : } 13.20 x 6.00 x 3.00 (Toilet Block)
- f) Flooring : } FF - 8.80 x 21.00 x 3.60
- g) Miscellaneous (Cracks if any) : } SF - 9.00 x 21.30 x 3.60
- TF - 24.80 x 9.20 x 3.60
6. Any Major defects notices which will render the building unsafe in any manner : Nil
7. Whether maintenance works have been done properly : Yes
8. Whether the structure is sound or not for conducting classes : Yes the structure is sound for conducting classes under normal weather conditions
- Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

## CERTIFICATE

Certified that the School was inspected by me on ..... 30/10/21 .....  
and found to be fit / unfit to conduct classes for the period ..... 2021-22 .....  
for the reason stated above.

Place: ..... Kannur .....

(Seal)

Date: ..... 11/11/21 .....



Assistant Engineer

ASSISTANT ENGINEER  
LOCAL SELF GOVERNMENT DEPARTMENT  
KANNUR MUNICIPAL CORPORATION

## FITNESS CERTIFICATE

To be filled by the Inspecting officer (Assistant Engineer) (Ref: G.O.MS 20/70/PWD Dt.23.01.1970)

- Name of School** : **Sree Narayana Vidya Mandir Senior Secondary School**
- Name of Officer : Lisina Puthussery
  - Location : Talap , Kannur north
  - Period for which the certificate is issued : 2021-2022 Academic year
  - Type of building : R C C Structure permanent – U P School Building
- GF-46.9x8.20x3.6m  
FF-46.9x8.20x3.6m  
SF-46.9x8.20x3.6m
- Foundation and basement : Nil
  - Superstructure : Nil
  - Doors and windows : Nil
  - Wood work wrought and put up : Nil
  - Roof : Nil
  - Flooring : Nil
  - Miscellaneous (Cracks if any) : Nil
  - Any major defects notices which will render the building unsafe if any manner : Nil
  - Whether maintenance works have been done Properly : Yes
- Whether the structure is sound or not for  
Conducting classes : The structure is sound for conducting Classes under normal weather conditions.

Note:1) The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.


2) Any additional observation deemed necessary for the certificate may be furnished separately with the certificate.

### CERTIFICATE

Certified that the School was inspected by me on 30/10/2021 and found to be fit/unfit to conduct classes for the period for the reason stated above.

Place : Kannur

Date : 30/10/2021

  
LISINA PUTHUSSEERY  
Assistant Engineer  
LSGD Engineering Wing  
Kannur Municipal Corporation  
Ph: 0497 2700141

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

## Name of the School

Sree Narayana Vidya Mandir, Senior's  
Secondary School, Talap, Kannur (L.P Block Only)

1. Name of the Officer
2. Location
3. Period for which the certificate is issued
4. Types of building
5. Nature of defect if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks if any)
6. Any Major defects notices which will render the building unsafe in any manner
7. Whether maintenance works have been done properly
8. Whether the structure is sound or not for conducting classes

: Priya R. Nair  
Assistant Engineer  
Pallikkunnu Zonal  
: 01-06-2021 to 31-05-2022  
: Permanent Multi Storied  
(Building No. V-1115-2002) L.P Block

G.F = 34 x 8.47 x 3.60 m  
F.F = 34 x 7.85 x 3.60 m  
S.F = 34 x 7.85 x 3.60 m  
T.F = 34 x 7.85 x 3.60 m

No

No

Yes

The structure is safe and sound  
for conducting classes under normal  
wind and weather conditions

- Note:-
1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
  2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

## CERTIFICATE

Certified that the School was inspected by me on ..... 29/10/2021 .....  
and found to be fit / unfit to conduct classes for the period 01-06-2021 to 31-05-22  
for the reason stated above.

Place: Kannur

Date: 29/10/2021



Priya R.  
Assistant Engineer  
Local Self Government Department  
Kannur Municipal Corporation  
Zonal Office - Pallikkunnu  
Assistant Engineer