

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Ambili. P. V

Sree Narayana Vidya Mandir
Thalap. Kannur. S.S. School,
Thalap

U.P. Block - 1999, No. 473/2 - 3 floors
 Main Block - 1992, No. 471/1 - 3 floors
 L.P. Block - R.No. V-115 - 3 floors

5. Period for which the certificate is issued

01/06/2026 to 31/03/2027 - 3 floors

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

Nil

7. Any major defects noticed which will render the building unsafe in any manner

No major defects were found

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

The structure is sound for conducting classes
under normal weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 04/07/2026 and
 found to be fit / unfit to conduct classes, for the period 01/06/2026 to 31/03/2027 for the
 reasons stated above.

Place: Kannur.

Date: 04/07/2026

(Seal)

Assistant Engineer

ASSISTANT ENGINEER
 LOCAL SELF GOVERNMENT DEPARTMENT
 KANNUR MUNICIPAL CORPORATION